



# Davidson Community Asbestos Site - 3/22/17



- Asbestos was not detected in CARB435 analysis or not detected in FBA analysis
- Trace asbestos detected in FBA sample
- Asbestos was detected at trace levels in CARB435 analysis; sample will be analyzed by FBA
- Asbestos detected at greater than or equal to 0.25%, or visibly observed on property
- ▲ Community identified buried asbestos
- Parcel with observed ACM

**Notes:**

ACM - Asbestos-containing material  
 CARB435 - California Air Resources Board Method 435  
 FBA - Fluidized bed analysis



Sources: Esri, HERE, DeLorme, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), MapmyIndia, NGCC, © OpenStreetMap contributors, and the GIS User Community  
 Esri, HERE, DeLorme, MapmyIndia, © OpenStreetMap contributors

Clayton Hayes